ECS Configuration Change Request

1. Originator	2. Log Date:	3. CCR #:	4. Rev:	5. Tel:	6. Rm #:	7. Dept.
Willard Selph	12/18/00	00-1169	—	301/883-4146	2107B	SED

8. CCR Title: Baseline AMASS 4.12.4

9. Originator Signature/Date	10. Class	11. Type:	12. Need Date: 12/22/00
Willard Selph 12-18-00	II	CCR	

13. Office Manager Signature/Date	14. Category of Change:	15. Priority: (If "Emergency" fill in Block 28).
R.P. Nurgendleay 12/18/00	Update ECS Baseline Doc.	Routine

16. Documentation/Drawings Impacted:	17. Schedule Impact:	18. CI(s) Affected: STMGT
910-TDA-003, 920-TDA-002 (mins SMC) on SGI Machines		

19. Release Affected by this Change:	20. Date due to Customer:	21. Estimated Cost:
6A, 5B		None - Under 100K

22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☒Other:
PSR

23. Problem: (use additional Sheets if necessary)
The new version of AMASS is needed to fix a CPU panic on IRIX 6.5.

24. Proposed Solution: (use additional sheets if necessary)
Install AMASS 4.12.3 on all new and upgraded IRIX 6.5 "drg" and appropriate "acg" hosts.

25. Alternate Solution: (use additional sheets if necessary)
N/A

26. Consequences if Change(s) are not approved: (use additional sheets if necessary)
Will hold up IRIX 6.5 migration.

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF ☒PVC ☒VATC ☒EDC ☒GSFC ☒LaRC ☒NSIDC ☐SMC ☐AK ☐JPL ☐EOC ☐IDG Test Cell ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. EDF/SCDV CCB Chair (Sign/Date): Byron V Peters 12/21/00	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB
33. M&O CCB Chair (Sign/Date): [signature] 12/21/00	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB

ORIGINAL